

Inspection Photos
Location Name: Jepsen 3
Facility ID: 106176



Photo 1 – 1999 Google Earth aerial imagery. Star indicates location of permitted Pit #106176.



Photo 2 – 2018 Google Earth aerial imagery and current facility layout.

Inspection Photos
Location Name: Jepsen 3
Facility ID: 106176



Photo 3 – Jepsen 3 wellhead (123-13646). Fencing and signage down. Well marked as long term shut in. Form 6 on file indicating P&A on 11/03/2017 (Document #401473775).



Photo 4 – Wellhead not cut and capped. Localized stained soil and fluid observed at wellhead.

Inspection Photos
Location Name: Jepsen 3
Facility ID: 106176



Photo 5 – Tank battery layout.



Photo 6 – Produced water vault and crude storage tank within secondary containment.

Inspection Photos
Location Name: Jepsen 3
Facility ID: 106176



Photo 7 – Drip pan on crude tank load out damaged.



Photo 8 – Tank marked out of service.