

Inspection Photos

Location Name: HSR-KNOX-65N67W /3SWSE

Location #: 330419



Colorado Oil & Gas Conservation Commission
40.42331, -104.87625, 1439.0m, 117°
2019/04/04 03:21:25 PM

Photo #1

HSR-Knox 15-3 (05-123-19095) Wellsite

Shut-In | SI



Colorado Oil & Gas Conservation Commission
40.42188, -104.87776, 1484.0m, 118°
2019/04/04 03:25:08 PM

Photo #2

HSR-Knox 15-3 Battery

Shut-down



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: HSR-KNOX-65N67W /3SWSE

Location #: 330419



Photo #3
HSR-Knox 15-3 Battery
Unused Equipment – Latrine
from prior FIR



Photo #4
HSR-Knox 15-3 Battery
Unused Equipment – Latrine
Removed

