

Inspection Photos
Location Name: Anderson 34R-403
Location ID: 432817



Photo 1 – Wellhead Sign



Photo 2 - Wellhead

Inspection Photos
Location Name: Anderson 34R-403
Location ID: 432817



Photo 3 – Wellhead sign



Photo 4 – 34R-343 Wellhead

Inspection Photos
Location Name: Anderson 34R-403
Location ID: 432817



Photo 5 – Wellhead Sign



Photo 6 – 34R-223 Wellhead

Inspection Photos
Location Name: Anderson 34R-403
Location ID: 432817



Photo 7 – 34R-203 Wellhead Sign is missing



Photo 8 – Anderson Production Equipment

Inspection Photos
Location Name: Anderson 34R-403
Location ID: 432817



Photo 9 – Production Tanks