

Inspection Photos

Location Name: EMERALD C 259

Location ID: 05-103-09043

Inspection: 679703584



Photo 1. Location looking north.



Photo 2. Well sign was lying on ground.



Inspection Photos

Location Name: EMERALD C 259

Location ID: 05-103-09043

Inspection: 679703584



Photo 3. Well casing covered with steel plate.



Photo 4. Well casing without cover.



Inspection Photos
Location Name: EMERALD C 259
Location ID: 05-103-09043
Inspection: 679703584





Photo 5. Well in infrared with a FLIR GF320 camera.

Photo 6. Well in infrared HSM with a FLIR GF320 camera.