

Inspection Photos

Location Name: Homer Deep Unit 9-41 Pad & Multiple associated Spills

Location ID: #432260 Spill IDs: #457569, #457570, #457869

Inspection Date: March 27, 2019



Photo #1 - Facility ID sign located at east entrance.

Photo #2 – Localized accumulation of oil-stained soil southwest of tank battery, looking SE.