

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 1. Non-reportable spill behind equipment building.



Photo 2. Non-reportable spill behind equipment building.

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 3. Non-reportable spill in front of triplex containment.



Photo 4. Close-up of Photo 3.

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 5. Free product and snowmelt inside triplex containment.



Photo 6. Free product and snowmelt inside triplex containment.

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 7. Free product and snowmelt inside triplex containment.



Photo 8. Free product and snowmelt inside triplex containment.

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 9. Free product and snowmelt inside triplex containment.



Photo 10. Free product and snowmelt inside triplex containment.

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 11. Free product and snowmelt inside triplex containment.



Photo 12. Free product and snowmelt inside triplex containment.

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 13. Free product and snowmelt inside triplex containment.



Photo 14. Free product inside triplex containment.

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 15. Free product inside triplex containment.



Photo 16. Free product inside triplex containment.

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 17. Non-reportable spill, stained soil outside containment.



Photo 18. Non-reportable spill, stained soil outside containment.

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 19. Non-reportable spill, stained soil outside containment.



Photo 20. Non-reportable spill, stained soil outside containment.

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 21. Non-reportable spill, stained soil outside containment.



Photo 22. Non-reportable spill, stained soil outside containment. Containment on left contains snowmelt, containment on right does not.