

Inspection Photos
Location Name: Dillard AB 10-07
Location ID: 415355



Photo 1: Pumpjack



Photo 2: Tank Battery

Inspection Photos
Location Name: Dillard AB 10-07
Location ID: 415355



Photo 3: No placarding on produced water tanks



Photo 4: No labeling on chemical barrels.

Inspection Photos
Location Name: Dillard AB 10-07
Location ID: 415355



Photo 5: Unused fencing.