

**Inspection Photos**  
**Location Name: Dillard USX AB 3-16**  
**Location ID: 310782**



**Photo 1: Pumpjack**



**Photo 2: No labeling on chemical barrels.**

**Inspection Photos**  
**Location Name: Dillard USX AB 3-16**  
**Location ID: 310782**



**Photo 3: Trash north of pump jack.**