

Inspection Photos
Location Name: Junction #22-2
Location ID: 336314



Photo 1 Junction #22-2 WH. **Well is TA** all production lines removed from WH



Photo 2 Junction #12-2 WH. **Well is SI**

Inspection Photos
Location Name: Junction #22-2
Location ID: 336314



Photo 3 Separators and unmarked, unused and not LOTO risers.



Photo 4 ECD

Inspection Photos
Location Name: Junction #22-2
Location ID: 336314



Photo 5 TNK BTRY



Photo 6 Volume label not legible. Visual impact paint is in disrepair. Tank visible from I-25 and in close proximity to office buildings.

Inspection Photos
Location Name: Junction #22-2
Location ID: 336314



Photo 7 Storm water reels on North side of location carrying sediment off location



Photo 8 Sediment carried off location from reels in previous picture #7

Inspection Photos
Location Name: Junction #22-2
Location ID: 336314



Photo 9 Storm water reels on North side of location



Photo 10 Location pic

Inspection Photos
Location Name: Junction #22-2
Location ID: 336314



Photo 11 Storm water reels on North west side of location carrying sediment off location



Photo 12 Sediment carried off location from reels is previous photo #11

Inspection Photos
Location Name: Junction #22-2
Location ID: 336314



Photo 13 Sales line to meter house is LOTO