

Inspection Photos
Location Name: Victoria U 1-12 JI
Location ID: 331120



Photo 1 WH all production equipment has been removed. Unused equipment: plunger lift and piping