

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/01/2019

Submitted Date:

04/01/2019

Document Number:

693700162**FIELD INSPECTION FORM**
 Loc ID 424899 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10261Name of Operator: BAYSWATER EXPLORATION & PRODUCTION LLCAddress: 730 17TH ST STE 500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Michelle Schuster		mschuster@bayswater.us	
Barbula, Don	303-912-4213	dbarbula@bayswater.us	
Brown, Mark	303-893-2503	mbrown@bayswater.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
445738	TANK BATTERY	AC	05/19/2016		-	Bears 4-30 and 5-30 Tank Battery	EI

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Gas Meter Run	# 1		corrective date
Comment:	Meter shed remains on location.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spill/Remediation:**

Comment: A produced water vessel was removed from the location. No Form 27 Site Investigation and Remediation Workplan was received for Director approval.

Corrective Action: Submit a Form 27 Site Investigation and Remediation Workplan with either: 1. soil sample results documenting compliance of the for produced water vessel location with Table 910-1; or 2. a workplan for conducting a site assessment at the former produced water vessel location.

Date: 04/30/2019

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401992247	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4780759
693700163	Bears5-30TankBatteryPhoto4-1-2019	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4780748