

Laramie Energy LLC
Api # 05-077-08725
Inspection # 675002132



Photo of location

Laramie Energy LLC
Api # 05-077-08725
Inspection # 675002132



Photo #2. Wellhead sign.



Photo # 3 Tank Battery

Laramie Energy LLC
Api # 05-077-08725
Inspection # 675002132



Photo #4 Tank needs paint and has a lot of rust.

Laramie Energy LLC
Api # 05-077-08725
Inspection # 675002132



Photo #5 Pit liner with large rip or tear




Photo #6 Pit liner not under tank .

Laramie Energy LLC
Api # 05-077-08725
Inspection # 675002132



Photo # 7. Erosion and sediment moving off location into a drainage ditch. (West side of location)



Photo #8 Erosion moving sediment off location on the West end of location into a drainage with no BMP

Laramie Energy LLC
Api # 05-077-08725
Inspection # 675002132



Photo #9 Sediment moving into a drainage ditch directed off location with no BMP in place on NE end of location



Photo #10 Erosion moving sediment directed off location with No BMP in place on NE end of location.