

Inspection Photos  
Operator: BP America  
Location/API #: 067-07010  
Date: 3-26-2019



Photo 1. View of the project area from the southwestern edge facing center.



Photo 2. View of the western project area from the southwestern project area facing northward. Revegetation is progressing within the revegetation areas.



Photo 3. View of the southern project area from the southwestern edge facing eastward.



Photo 4. View of the northeastern project area facing southeastward. What appears to be surface owner equipment is stored within the northeastern project area.