

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-08810**  
**Date: 3-26-2019**



Photo 1. View of the project area from the southeastern corner of the working area facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of erosional channel and tunneling approximately 1.5 feet wide and 2 feet deep within the southwestern project area.



Photo 5. View of hose debris within the interim reclamation area.