

Inspection Photos  
Operator: BP America  
Location/API #: 067-08954  
Date: 3-26-2019



Photo 1. View of the project area from the northeastern edge facing center.



Photo 2. View of erosional rilling and sediment trap that are not functioning, north of the well pad entrance.



Photo 3. View of cobble run-down that appears to be functioning, south of the well pad entrance.



Photo 4. View of the southern project area from the southeastern corner facing westward.



Photo 5. View of tank that does not appear to be in use.