

COMPLIANCE FOLLOW UP FORM

INFORMATION

Name colen@horizonenvservices.com
Date Tue Apr 02 2019
Well Name JONES GAS UNIT 34-16 2
API Number 50670897100
Select State Colorado
Work type COGCC Inspection AR
Action Complete Compliance Inspection Actions
Clean up Operator Debris

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Additional photos

Additional photos



Completed work description

Removed unused equipment on location.