

Final Reclamation and Stormwater Inspection

March 28, 2019

Operator: GREAT WESTERN OPERATING COMPANY LLC # 10110

Location ID: 424020

Inspection Document #: 674902708

Weld County, CO

SENW Section 2 T3N R68W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY /3N68W2

Location ID: 424020



Photo 1. Photo taken from the access road, facing West. Appears the access road remains on location.



Photo 2. Photo taken from the location, facing East. Photo depicts the removal of all equipment has been performed. The gravel remains on location and no other reclamation activities were observed.

Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY /3N68W2

Location ID: 424020



Photo 3. Photo taken from the location, facing East. See comments from Photo 2.



Photo 4. Photo taken from the location, facing South. Appears there is erosion on location.

Inspection Photos

Location Name: GREAT WESTERN OPERATING COMPANY /3N68W2

Location ID: 424020



Photo 5. Photo taken from the location, facing North. See comments from Photo 2.



Photo 6. Photo taken from the location, facing Northeast. See comments from Photo 2.