

Inspection Photos

Loc#335547

Operator: Ursa

Inspection Number: 692400827

Inspection Date: 3/26/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:

Overview of Location from Southwest to Northeast.

March 26, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Gentry Loc#335547



Photo#2:

One swale / ditch area is filling with sediment which may be moving from surrounding Interim Rec areas not yet stabilized with vegetation

March 26, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Gentry Loc#335547



Photo#3:

Two anchors; markers broken off; these appeared to be marked for repair.

March 26, 2019



Photo#4:

Two anchors; markers broken off; these appeared to be marked for repair.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Gentry Loc#335547



Photo#5:

Cut Bank / slope behind Tanks needs to be stabilized.



Photo#6:

Cut Bank / slope behind Tanks needs to be stabilized.

March 26, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa Gentry Loc#335547