

Inspection Photos

Loc#335539

Operator: Ursa

Inspection Number: 692400828

Inspection Date: 3/26/19





Photo#1:
Overview of Location from East to West.

March 26, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa McPherson Loc#335539



Photo#2:

There is an unsecured cover on Rat Hole (tentatively identified as such by Operator employee) adjacent to XX Well API#045-14474 with Conductor set.

Photo#3: .

March 26, 2019



Photo#4:

Area on North side of site, running N > S through Interim Reclamation (maybe pipeline path) is bare of vegetation, eroding, and transporting sediment.

March 26, 2019

Photo#5:



Photo#6:
Ditch on West side of Access Road has failed

March 26, 2019

Photo#7:
Ditch on West side of Access Road has failed



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Ursa McPherson Loc#335539