

Final Reclamation and Stormwater Inspection

March 28, 2019

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 330153

Inspection Document #: 674902711

Weld County, CO

SWSW Section 5 T3N R67W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: KERR MCGEE /3N67W5
Location ID: 330153



Photo 1. Photo taken from the access road , facing North. Appears the Operator has left the gate and first part of the access road intact.



Photo 2. Photo taken from the location, facing North. See comments from Photo 1.

Inspection Photos
Location Name: KERR MCGEE /3N67W5
Location ID: 330153



Photo 3. Photo taken from the location, facing North.
See comments from Photo 1.



Photo 4. Photo taken from the location, facing North.
Appears the Operator has performed final reclamation activities, with the evidence of drilling rows .

Inspection Photos
Location Name: KERR MCGEE /3N67W5
Location ID: 330153



Photo 5. Photo taken from the location, facing North. See comments from Photo 4.



Photo 6. Photo taken from the location, facing West. See comments from Photo 4.