

# Final Reclamation and Stormwater Inspection

March 28, 2019

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 329006

Inspection Document #: 674902712

Weld County, CO

NENW Section 8 T3N R67W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: KERR MCGEE /3N67W8  
Location ID: 329006



**Photo 1.** Photo taken from access road looking toward the location, facing North. Appears there is erosion on location.



**Photo 2.** Photo taken from the location, facing North. Appears Operator has performed final reclamation activities with the removal of all equipment from the P&A well.