

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/03/2019

Submitted Date:

04/04/2019

Document Number:

697300040**FIELD INSPECTION FORM**Loc ID 408026 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 52250Name of Operator: MACHII-ROSS PETROLEUM COAddress: 2425 OLYMPIC BLVD #4000WCity: SANTA MONICA State: CA Zip: 90404-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Rehkop, Neil	310-465-6590/10127	karpetroleum@att.net	
Sato, Edward	310-948-2627/27742	esato_tsk@verizon.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
244616	WELL	PA	04/30/2001	OW	123-12411	KLEIN 1-30J	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. COGCC Inspection in response to spill discovered by Anadarko during a safety prep of the Klein 1-30J wellhead. See comments and corrective actions under Spills/Releases.

Corrective actions are due within 72 hours

Inspected Facilities									
Facility ID:	244616	Type:	WELL	API Number:	123-12411	Status:	PA	Insp. Status:	EI

--

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: _____

Comment: A historical spill was discovered by Anadarko during a safety prep of the Klein 1-30J wellhead. Attached analytical report indicates impacts are above Table 910-1 standards for both soil and groundwater.

Corrective Action: Operator shall submit a COGCC Spill/Release Report, Form 19 with the Initial Report information as soon as practicable but not later than 72 hours per Rule 906.b. Within 10 days (by May 14, 2019), submit a Form 27 Site Investigation and Remediation Workplan.

Date: 04/07/2019

Reportable: YES

GPS: Lat _____ Long _____

Proximity to Surface Water: 46

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401996341	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4784318
697300041	Analytical	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4784314
697300042	Site Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4784315