

**Inspection Photos**  
**Location Name: 70 RANCH USX BB /09-99HZ**  
**Location #: 302881**



Colorado Oil & Gas Conservation Commission  
40.42058, -104.44836, 1426.0m, 308°  
2019/04/11 02:40:19 PM

**Photo #1**

**70 Ranch USX BB 09-99HZ (05-123-30639) Wellsite**

**Temporarily Abandoned | TA**

**Unused Equipment**



Colorado Oil & Gas Conservation Commission  
40.4201, -104.44835, 1418.0m, 159°  
2019/04/11 02:17:27 PM

**Photo #2**

**70 Ranch 11-9 (05-123-29970) Wellsite**

**Plugged & Abandoned | PA**

**≈ 10 yds.**



**Inspection Photos**  
**Location Name: 70 RANCH USX BB /09-99HZ**  
**Location #: 302881**



**Photo #3**  
**70 Ranch USX BB 09-99HZ Battery**  
**Shut-down**  
*Former Battery for 70 Ranch 11-9 PA well*



**Photo #4**  
**70 Ranch USX BB 09-99HZ Battery**  
**Unused Equipment**  
***Gas meter run, risers, automation***