

Inspection Photos

Location Name: WEAVER RIDGE 23-14

Location ID: 05-103-10668

Inspection: 679703667



Photo 1. Location looking northeast.



Photo 2. Unmarked deadman.



Inspection Photos

Location Name: WEAVER RIDGE 23-14

Location ID: 05-103-10668

Inspection: 679703667



Photo 3. Full well head cellar and surrounding oily waste on ground.