

**Inspection Photos**  
**Location Name: WEAVER RIDGE 23-16**  
**Location ID: 05-103-10520**  
**Inspection: 679703669**



**Photo 1. Location looking north.**



**Photo 2. Tank label without capacity volume.**