

Inspection Photos
Location Name: AC #14-10
Location ID: 308614



Photo 1 Sep/meter house 25bbl production tank



Photo 2 Unused equipment (solar panel)

Inspection Photos
Location Name: AC #14-10
Location ID: 308614



Photo 3 Bird netting on 20bbl tank secondary containment in disrepair.



Photo 4 HYD skid and WH

Inspection Photos
Location Name: AC #14-10
Location ID: 308614



Photo 5 Stained soil around WH it appears from HYD lines



Photo 6 Loc pic