

Inspection Photos
Location Name: AC #24-4
Location ID:308821



Photo 1 Sep/meter house. No well sign. Trash (door)



Photo 2 30bbl Produced water tank. Unused equipment 1' pipe

Inspection Photos
Location Name: AC #24-4
Location ID:308821



Photo 3 Stained soil around liquid ring riser



Photo 4 Liquid ring skid almost full possible storm water issue.

Inspection Photos
Location Name: AC #24-4
Location ID:308821



Photo 5 WH and HYD skid sound walls



Photo 6 guy line anchor not properly marked.