

Inspection Photos
Location Name: AC# 24-08
Location ID:308930



Photo 1 Sep/meter house



Photo 2 WH and HYD skid sound walls

Inspection Photos
Location Name: AC# 24-08
Location ID: 308930



Photo 3 Liquid ring



Photo 4 30bbl production tank with bull plug on load line

Inspection Photos
Location Name: AC# 24-08
Location ID: 308930



Photo 5 Stained soil around HYD skid



Photo 6 Stained soil around Liquid ring

Inspection Photos
Location Name: AC# 24-08
Location ID: 308930



Photo 7 Unused equipment (power poles and wire)