

Laramie Energy LLC
Api # 05-077-08668
Inspection # 675002153



Photo of location at entrance

Laramie Energy LLC
Api # 05-077-08668
Inspection # 675002153



Photo of tank battery



Photo of wellhead

Laramie Energy LLC
Api # 05-077-08668
Inspection # 675002153



**Hole and evidence of erosion moving soil and storm water
off the SE side edge of location**



**Hole and evidence of erosion moving soil and storm water
off the SE side edge of location**

Laramie Energy LLC
Api # 05-077-08668
Inspection # 675002153



Unstable berm allowing erosion to move soil and storm water on north side of location



Evidence of unstable ground moving top soil and storm water on East side of location,