

Laramie Energy LLC
Api # 05-077-08772
Inspection # 675002156



Photo of location at entrance

Laramie Energy LLC
Api # 05-077-08772
Inspection # 675002156



Photo of tank battery



Photo of wellhead

Laramie Energy LLC
Api # 05-077-08772
Inspection # 675002156



Evidence of erosion moving soil and storm water off the west side edge of location



Evidence of erosion moving soil and storm water off the west side edge of location at the entrance.