

**Laramie Energy LLC**  
**Api # 05-077-08232**  
**Inspection # 675002164**



**Photo of location at entrance**

**Laramie Energy LLC**  
**Api # 05-077-08232**  
**Inspection # 675002164**



**Photo of tank battery**



**Photo of wellhead**



**Laramie Energy LLC**  
**Api # 05-077-08232**  
**Inspection # 675002164**



**Sediment moving down access road onto location**



**BMP full of sediment on West side of entrance road.**



**Laramie Energy LLC**  
**Api # 05-077-08232**  
**Inspection # 675002164**



**No BMP in place or maintained to keep erosion from leaving access road.**



**Signs of erosion moving sediment off location**



**Laramie Energy LLC**  
**Api # 05-077-08232**  
**Inspection # 675002164**



**No BMP in place or maintained to keep erosion from leaving access road.**



**View at entrance of location**



**Laramie Energy LLC**  
**Api # 05-077-08232**  
**Inspection # 675002164**



**Sink hole in middle of location**



**Sink hole in middle of location**