

Inspection Photos
Location Name: AC #29-7
Location ID: 307287



Colorado Oil and Gas Conservation Commission
37.05705, -104.9079, 2459.5m
Apr 12, 2019 08:37:11

Photo 1 Sep/Meter house



Colorado Oil and Gas Conservation Commission
37.05705, -104.90791, 2458.2m
Apr 12, 2019 08:37:32

Photo 2 30bbl produced water tank

Inspection Photos
Location Name: AC #29-7
Location ID: 307287



Photo 3 PU. Packing appears to be leaking fluid has travel approximately 20ft on location.



Photo 4 produced water pit