

Inspection Photos
Location Name: AC# 29-06
Location ID: 309244



Photo 1 Sep/meter house



Photo 2 WH and HYD motor skid

Inspection Photos
Location Name: AC# 29-06
Location ID: 309244



Photo 3 Packing leaking at time of inspection



Photo 4 Stained soil around HYD motor skid

Inspection Photos
Location Name: AC# 29-06
Location ID: 309244



Photo 5 Stained soil around HYD motor skid



Photo 6 Stained soil around HYD motor skid

Inspection Photos
Location Name: AC# 29-06
Location ID: 309244




Photo 7 Stained soil Under and around drain for separator



Photo 8 Produced water pit