

Inspection Photos
Location Name: HR#33-4X
Location ID: 302064



Photo 1 sep/meter house



Photo 1 PU and electric panel.

Inspection Photos
Location Name: HR#33-4X
Location ID: 302064



Photo 3 Packing on well head appears to be leaking and traveling down location

Photo 4 Produced water pit.