

Inspection Photos

4/12/2019

Operator: FRITZLER RESOURCES INC - 31257

Location ID: 316908

Inspection Doc. Number: 682504727

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photos taken from the well, facing west. Photo shows pipe and equipment not needed for production activity being stored on the location.

Inspection Photos
Operator: FRITZLER RESOURCES INC - 31257
Location ID: 316908



Photo 2: Photos taken from the well, facing west. Photo shows pipe and equipment not needed for production activity being stored on the location.

Inspection Photos
Operator: FRITZLER RESOURCES INC - 31257
Location ID: 316908



Photo 3: Photos taken from the well, facing west. Photo shows pipe and equipment not needed for production activity being stored on the location.



Photo 4: Photos taken from the well, facing west. Photo shows pipe and equipment not needed for production activity being stored on the location.

Inspection Photos
Operator: FRITZLER RESOURCES INC - 31257
Location ID: 316908



Photo 5: Photos taken from the well, facing west. Photo shows pipe and equipment not needed for production activity being stored on the location.

Inspection Photos
Operator: FRITZLER RESOURCES INC - 31257
Location ID: 316908



Photo 6: Photo taken from the well. Photo shows chemicals/fluids are being discharged from the well. Photo also shows contaminated soils.