

Inspection Photos

Location Name: APACHE CANYON 25-04

API #: 05-071-06133

Insp. Doc. # 695100502



Colorado Oil & Gas Conservation Commission
37.0593, -104.95415, 2427.0m, 275°
2019/04/12 14:01:35

PHOTO 1: LOCATION



Colorado Oil & Gas Conservation Commission
37.05955, -104.95412, 2437.0m, 313°
2019/04/12 14:02:00

PHOTO 2: METER HOUSE/WELL SIGN

Inspection Photos
Location Name: APACHE CANYON 25-04
API #: 05-071-06133
Insp. Doc. # 695100502



PHOTO 3: IT APPEARS THAT THERE WAS AN ATTEMPT TO REMOVE SOME IMPACTED SOIL IN THE NEAR PAST AS THERE IS SOIL REMOVED FROM THE SOUTH SIDE OF COMPRESSOR SKID BUT AS SHOWN IN THIS PHOTO SOME OF THE IMPACTED SOIL WAS NOT REMOVED AND WAS COVERED UP WITH CLEAN GRAVEL.



PHOTO 4: COMPRESSOR SKID CONTAINMENT IS FULL OF OILY WATER AND IS SPILLING OVER ON LOCATION IMPACTING SOIL ON NORTHWEST CORNER OF COMPRESSOR SKID.