

Laramie Energy LLC  
Api # 05-077-09095  
Inspection # 675002170



Photo of location at entrance

Laramie Energy LLC  
Api # 05-077-09095  
Inspection # 675002170



Photo of tank battery



Photo of wellhead

Laramie Energy LLC  
Api # 05-077-09095  
Inspection # 675002170



**Storm water leaving location with no BMP to catch sediment along the access road**

**Storm water leaving location with no BMP to catch sediment along the access road**

Laramie Energy LLC  
Api # 05-077-09095  
Inspection # 675002170



**Storm water leaving location with no BMP to catch sediment along the access road**

**Storm water leaving location with no BMP to catch sediment along the access road**

Laramie Energy LLC  
Api # 05-077-09095  
Inspection # 675002170



Holes in containment liner

Holes in containment liner

Laramie Energy LLC  
Api # 05-077-09095  
Inspection # 675002170



Holes in containment liner

Laramie Energy LLC  
Api # 05-077-09095  
Inspection # 675002170



Trash on location



Unused equipment on location