

Inspection # 675002173

Photo of location at entrance

Laramie Energy LLC
Api # 05-077-08573
Inspection # 675002173



Photo of tank battery




Photo of wellhead

Laramie Energy LLC
Api # 05-077-08573
Inspection # 675002173



Storm water moving sediment off location with no BMP



Storm water leaving location with no BMP to catch sediment

Laramie Energy LLC
Api # 05-077-08573
Inspection # 675002173



Trash or unused equipment on location.



BMP needs maintenances.

Laramie Energy LLC
Api # 05-077-08573
Inspection # 675002173



Trash on location



Erosion on side of tank moving soil down the hill

Laramie Energy LLC
Api # 05-077-08573
Inspection # 675002173



Trash on location



Trash on location