

Inspection Photos
Location Name: PCW 33-5
API #: 05-071-06334
Insp. Doc. # 695100507



PHOTO 1: WELLHEAD



PHOTO 2: METER HOUSE/WELL SIGN

Inspection Photos
Location Name: PCW 33-5
API #: 05-071-06334
Insp. Doc. # 695100507



PHOTO 3: DEBREE ON LOCATION. A SECTION OF WELLHEAD HOUSE WALL HAS FALLEN OF AND IS ON THE GROUND NEAR SEPARATOR

