

Inspection Photos
Location Name: PCW 23-9 FOLLOWUP
API #: 05-071-06325
Insp. Doc. # 695100510



PHOTO 1: LOCATION



PHOTO 2: METER HOUSE/WELL SIGN

Inspection Photos

Location Name: PCW 23-9 FOLLOWUP

API #: 05-071-06325

Insp. Doc. # 695100510



**PHOTO 3: PACKING IS STILL LEAKING CAUSING APP. 3'
ROUND AREA OF IMPACTED SOIL AROUND WELLHEAD**

