

Inspection Photos
Location Name: Mckay AB 02-13
Location ID: 413503



Photo 1: Pump Jack



Photo 2: Tank Battery

Inspection Photos
Location Name: Mckay AB 02-13
Location ID: 413503




Photo 3: (3) north tank labels not legible.



Photo 4: Unused equipment

Inspection Photos
Location Name: Mckay AB 02-13
Location ID: 413503



Photo 5: Unused equipment south of pump jack.