

Inspection Photos
Operator: Enervest Operating
Location/API #: 067-07316
Date: 4-9-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southwestern project area from the southwestern corner facing southeastward.



Photo 3. View of erosional channel approximately 1 to 2 feet wide and deep, in the southern project area, facing upslope toward the working area. Notebook placed in channel for scale.



Photo 4. View of another erosional channel approximately 2 feet wide and deep within the southern project area.