

Inspection Photos
Location Name: Hankins #1
Location ID: 318634



Photo 1 WH. Well is producing



Photo 2 TNK BTRY

Inspection Photos
Location Name: Hankins #1
Location ID: 318634



Photo 3 unmarked, unused risers



Photo 4 stained soil around risers next to pig launcher.

Inspection Photos
Location Name: Hankins #1
Location ID: 318634



Photo 5 Stained soil inside sep house



Photo 6 sep and meter run.

Inspection Photos
Location Name: Hankins #1
Location ID: 318634



Photo 7 Unmarked unused and not LOTO Riser

Photo 8 50 bbl produced water vault.

Inspection Photos
Location Name: Hankins #1
Location ID: 318634



Photo 9 Inadequate berm around produced water tank.

Photo 10 Wildlife issue no bird netting on top of produced water vault.