

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/16/2019

Submitted Date:

04/17/2019

Document Number:

675002177**FIELD INSPECTION FORM**

Loc ID 451421	Inspector Name: Wentzel, Dougo	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 26 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> OGCC Operator Number: <u>10433</u> Name of Operator: <u>LARAMIE ENERGY LLC</u> Address: <u>1401 SEVENTEENTH STREET #1401</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	<a href="#">All Inspections</a>
Clark, Chris		cogccnotifications@laramie-energy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451416	WELL	PR	02/15/2018	OW	077-10445	Bruton 30-04E	PR
451417	WELL	PR	02/15/2018	GW	077-10446	Bruton 30-03W	PR
451418	WELL	PR	06/01/2018	GW	077-10447	Bruton 30-11W	PR
451419	WELL	PR	06/01/2018	GW	077-10448	Bruton 30-12E	PR
451420	WELL	PR	03/01/2018	GW	077-10449	Bruton 30-09E	PR
451423	WELL	PR	03/01/2018	GW	077-10450	Bruton 30-08W	PR
451424	WELL	PR	03/01/2018	GW	077-10451	Bruton 30-05E	PR
451425	WELL	PR	06/01/2018	GW	077-10452	Bruton 30-11E	PR
451426	WELL	PR	03/01/2018	OW	077-10453	Bruton 30-06W	PR
451427	WELL	PR	02/15/2018	GW	077-10454	Bruton 30-01W	PR
451428	WELL	PR	03/01/2018	GW	077-10455	Bruton 30-06E	PR
451429	WELL	PR	07/07/2018	GW	077-10456	Bruton 30-10E	PR
451430	WELL	PR	05/01/2018	OW	077-10457	Bruton 30-04W	PR
451432	WELL	PR	03/01/2018	GW	077-10458	Bruton 30-09W	PR
451433	WELL	PR	06/01/2018	GW	077-10459	Bruton 30-13E	PR
451434	WELL	PR	07/07/2018	OG	077-10460	Bruton 30-13W	PR
451435	WELL	PR	06/01/2018	GW	077-10461	Bruton 30-12W	PR
451436	WELL	PR	03/01/2018	OW	077-10462	Bruton 30-05W	PR
451437	WELL	PR	02/15/2018	GW	077-10463	Bruton 30-02W	PR
451440	WELL	PR	07/07/2018	GW	077-10464	Bruton 30-10W	PR

**General Comment:**

This is a follow up inspection from doc#675002104 Dated 4/1/19 and 675002085 dated 3/26/19  
All corrective actions have been submitted and are in progress or have been satisfied from previous inspections.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Tank battery sign not apparent to location. At the option of the operator, or at the request of local emergency response authorities, the sign may be placed at the intersection of the lease access road with a public, farm or ranch road if the referenced battery is readily apparent from such location.		
Corrective Action:	Install sign to comply with Rule 210.b		Date: 05/17/2019
Emergency Contact Number:			
Comment:	911/ 1-800-891-6191		
Corrective Action:			Date:
<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Storage of 5 gallon buckets on location		
Corrective Action:	Comply with Rule 603.f .		Date: 05/17/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Equipment:</b>			
Type: Plunger Lift	# 20		corrective date
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 20		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
AMINE	3	<50 BBLS	PLASTIC AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspector Name: Wentzel, Dougo

Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	451416	Type:	WELL	API Number:	077-10445	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	451417	Type:	WELL	API Number:	077-10446	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	451418	Type:	WELL	API Number:	077-10447	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	451419	Type:	WELL	API Number:	077-10448	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	451420	Type:	WELL	API Number:	077-10449	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	451423	Type:	WELL	API Number:	077-10450	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	451424	Type:	WELL	API Number:	077-10451	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing Well								
Corrective Action:						Date:			
Facility ID:	451425	Type:	WELL	API Number:	077-10452	Status:	PR	Insp. Status:	PR

<u>Producing Well</u>			
Comment:	Producing Well		
Corrective Action:		Date:	
Facility ID: 451426    Type: WELL    API Number: 077-10453    Status: PR    Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Producing Well		
Corrective Action:		Date:	
Facility ID: 451427    Type: WELL    API Number: 077-10454    Status: PR    Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Producing Well		
Corrective Action:		Date:	
Facility ID: 451428    Type: WELL    API Number: 077-10455    Status: PR    Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Producing Well		
Corrective Action:		Date:	
Facility ID: 451429    Type: WELL    API Number: 077-10456    Status: PR    Insp. Status: PR			
<u>Producing Well</u>			
Comment:			
Corrective Action:		Date:	
Facility ID: 451430    Type: WELL    API Number: 077-10457    Status: PR    Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Producing Well		
Corrective Action:		Date:	
Facility ID: 451432    Type: WELL    API Number: 077-10458    Status: PR    Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Producing Well		
Corrective Action:		Date:	
Facility ID: 451433    Type: WELL    API Number: 077-10459    Status: PR    Insp. Status: PR			
<u>Producing Well</u>			
Comment:	Producing Well		

Corrective Action:		Date:	
Facility ID: <u>451434</u> Type: <u>WELL</u> API Number: <u>077-10460</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	<a href="#">Producing Well</a>		
Corrective Action:		Date:	
Facility ID: <u>451435</u> Type: <u>WELL</u> API Number: <u>077-10461</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	<a href="#">Producing Well</a>		
Corrective Action:		Date:	
Facility ID: <u>451436</u> Type: <u>WELL</u> API Number: <u>077-10462</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	<a href="#">Producing Well</a>		
Corrective Action:		Date:	
Facility ID: <u>451437</u> Type: <u>WELL</u> API Number: <u>077-10463</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	<a href="#">Producing Well</a>		
Corrective Action:		Date:	
Facility ID: <u>451440</u> Type: <u>WELL</u> API Number: <u>077-10464</u> Status: <u>PR</u> Insp. Status: <u>PR</u>			
<b><u>Producing Well</u></b>			
Comment:	<a href="#">Producing Well</a>		
Corrective Action:		Date:	



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Sediment Traps	Pass			
		Culverts	Pass			
Gravel	Pass					
		Check Dams	Pass			
Drains	Pass					
Sediment Traps	Pass					
Ditches	Pass					
		Ditches	Pass			
		Gravel	Pass			
Waddles	Pass					
Compaction	Pass					
Check Dams	Pass					
Berms	Pass					

Comment:

Corrective Action:

Date:

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675002178	Inspection 675002177 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4798465">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4798465</a>