

# Final Reclamation and Stormwater Inspection

March 29, 2019

Operator: KERR MCGEE OIL & GAS # 47120

Location ID: 320307

Inspection Document #: 674902775

Adams County, CO

NWSW Section 23 T1S R68W

Russell Beam  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: KERR MCGEE /1S68W23  
Location ID: 320307



**Photo 1.** Photo taken from the location, facing West. Appears the fence and access road remain.



**Photo 2.** Photo taken from the location, facing West. See comments from Photo 1.



Inspection Photos  
Location Name: KERR MCGEE /1S68W23  
Location ID: 320307



**Photo 3.** Photo taken from the location, facing North. Appears Operator has performed final reclamation activities with the evidence of drill rows. However, the reclamation is not at percent cover and has non-uniform establishment of vegetation cover.



**Photo 4.** Photo taken from the location. A List B CO Noxious weed, Scotch Thistle, was observed at the location.

Inspection Photos  
Location Name: KERR MCGEE /1S68W23  
Location ID: 320307



**Photo 5.** Photo taken from the location, facing East. See comments from Photos 1 and 3.



**Photo 6.** Photo taken from the location, facing West. Appears there is still equipment left on site.



Inspection Photos  
Location Name: KERR MCGEE /1S68W23  
Location ID: 320307



**Photo 7.** Photo taken from the location, facing North.  
See comments from Photo 6.



**Photo 8.** Photo taken from the location, facing East. See  
comments from Photos 1 and 3.