

Inspection Photos

API#103-05621

Operator: Hayes Petroleum

Inspection Number: 692400898

Inspection Date: 3/29/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to West.

March 29, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Hayes Petroleum PA Calco Hayes 18 API#103-05621



Photo#2:
Overview of Location to South.

March 29, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Hayes Petroleum PA Calco Hayes 18 API#103-05621



Photo#3:
View of valve at backside of tank.

March 29, 2019



Photo#4:
Pit area on Southwest corner of site.



Photo#5:
Shed at South edge of site.

March 29, 2019



Photo#6:
View to East over West side of site.