

Inspection Photos
Location Name: CALLISTER GOVERNMENT 4
Location ID: 05-103-06358
Inspection: 679703766



Photo 1. Location looking north.

Photo 2. Two uncapped risers.

