

Inspection Photos

Location Name: DRAGON TRAIL UNIT 1040

Location ID: 05-103-07213

Inspection: 679703774



Photo 1. Location looking northeast.



Photo 2. Rock slide blocking off road 100 yards from location.



Inspection Photos

Location Name: DRAGON TRAIL UNIT 1040

Location ID: 05-103-07213

Inspection: 679703774



Photo 3. Torn secondary containment liner.



Photo 4. Tank located 50' from Little Bull Draw drainage.



Inspection Photos

Location Name: DRAGON TRAIL UNIT 1040

Location ID: 05-103-07213

Inspection: 679703774



Photo 5. Breached berm at southeast corner of location.



Photo 6. Tracking off location.



Inspection Photos

Location Name: DRAGON TRAIL UNIT 1040

Location ID: 05-103-07213

Inspection: 679703774



Photo 7. Tank battery sign missing "911".

