

Inspection Photos
Location Name: 70 RANCH USX BB /35-08
Location #: 416463




Photo #1

70 Ranch USX BB 35-08 (05-123-31453) Wellsite

Temporarily Abandoned | TA

Unused Equipment

Fittings & pipe



Photo #2

70 Ranch USX BB 35-08, 35-01P, 35-02 Battery site

Abandoned

Unused Equipment

Gas meter run, riser