

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/18/2019

Submitted Date:

04/18/2019

Document Number:

696100801**FIELD INSPECTION FORM**Loc ID 415637 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
415632	WELL	SI	10/01/2017	OW	123-31139	70 RANCH USX BB 35-02	PA

General Comment:This is a **PLUGGED & ABANDONED WELL** Inspection.

Well: PA

Battery: Abandoned & ALL equipment removed except for Gas meter run & riser.

Abandoned Battery SE corner GPS coordinates: 40.359019, -104.397735

Reclamation progressing.

Abandoned Centralized Battery formerly served 3 Location IDs (416463, 415988, 415367). (1-well:TA, 1-well: TA, 1-well: PA).

Location**Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:			

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 415632 Type: WELL API Number: 123-31139 Status: SI Insp. Status: PA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well appears to have been P&A.
 Form 6 #401690899 indicates plugging date: 07/18/2018. (Approval Pending).
 Reclamation progressing.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>On THU APR 18, 2019 at approximately 13:20 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: 70 Ranch USX BB /35-02 Location ID: 415637 Location County: Weld County, Colorado While there, I observed: 1-Well(s) PA. Routine Inspection. No Corrective Actions observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	04/18/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696100802	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4800508